


Setting up the Dock


The setup instructions below are designated for **Lenovo ThinkPad Thunderbolt 3 Dock Gen 2 devices**.

1. Connect the Dock to Your Computer


- Connect one end of the Thunderbolt 3 cable to the dock.




- Connect the other end of the Thunderbolt 3 cable to the computer.




- Connect the power cord to the 135-watt ac power adapter.



- Connect the 135-watt ac power adapter to the power connector on the dock.



- Connect the power cord to an electrical outlet



If you have any questions or need assistance, please contact us.